Noxudol®

Treatment diagram

Volvo V 70 **Model 2003**

Floor level





Engine compartment:

Cowl: Treatment via 2 drill holes in plastic grille. Treatment behind spring struts, on top of longitudinal members, under fluid reservoir, electronic box, fuse box and air filter box. Treatment of locking plate and top member in wing. See fig. 3 and 4.



Front wing: Treatment of top member in wing via existing gap.



Engine compartment: Treatment behind spring struts, on top of longitudinal member, under electronic box, air filter box.



A-pillar and front wing: Treat via 2 drilled holes. Drill level right above and right below door hinges. Treatment of front wing with lance, from clearing between A-pilar and wing/door.



Front door: Treat via 3 drilled holes. Centre drilling: Drill level with door lock. Lower drill hole: Drill level with upper edge of plate flange



Open lug, remove felt, treat around tail

Treat via 2 drilled holes. Lower drill

hole level with SIPS-logo.



Rear panel: Treat via 3 drilled holes. See fig. 12 for correct drilling level.

Rear door:



Tailgate: No treatment, rustproof materials.



B-pillar:

VOLVO



Area





C Existing hole

light.

Rear wing:

Dom on detail Cuinting plugged hole







Treat via 2 drill holes and drain hole.



C-pillar: Treat via 3 drilled holes. Lower drill hole level with SIPS-logo. See fig 10 for correct drilling in top.



Rear panel: Fig: drilling at correct level.

Noxudol®

Treatment diagram

Volvo V 70 **Model 2003**

General view of underside





Wheel arch rear: Drill 2 holes for correct treatment. Open lug, remove felt, treat around tail light.



Panel sectional view: Fig: drilling at correct level.



4 drill holes to treat outer panel and 3 drill holes and existing plug to treat inner panel. See fig 3 for drilling at correct level.



Wheel arch front: Treatment via 2 drill holes and behind wheel arch liner where possible.



Longitudinal member/reinforcement in wheel arch front: Treat via 2 drilled holes.



Treatment via 3 existing holes. See

also fig. 7.



Longitudinal members centre: Treat via existing and plugged holes. See fig. 10 for drilling at correct level.





Longitudinal member rear: 1 drill hole each side through cover plate.

Longitudinal member after wheel arch rear: Treat via 1 drilled hole and existing plugged hole.



Longitudinal member front: Treat via existing holes.



Longitudinal member front: Treat via existing plugged hole.







O Existing hole







Cross member above rear axle assembly: Treat via existing holes.





Longitudinal member centre: Fig. for drillings at correct level.

Reinforcement before wheel arch front: Treat via 3 existing plugged holes.